

VEHICLE INSPECTION REPORT

EA13BYF

Ford Galaxy 2.0 TDCi 163 Titanium X 5dr

nama
GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	23/04/2013	Body Style	MPV	Last service miles	165,363
Year	2013	Keys	2	MOT Due	11/04/2027
Mileage	167,734 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	14		
VIN	WF0MXXGBWMCS79924	Last service date	02/04/2026		

LAST SERVICE 02/04/2026 @ 165,363 MILES (14 SERVICES, 3 MAIN DEALER)

Tyres

NSF	FARROAD	4.0mm
NSR	BUDGET	5.0mm
OSF	FARROAD	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Cruise control
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Central locking
- Front parking sensor
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Cracked
Over 25mm



4: Wheel nsf
Scratched
Over 50mm



5: Sill ns
Dented
With Paint Damage



6: Wing nsf
Scratched
Rusted



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Chipped
Edge Chip



9: Wheel osr
Scratched
Up To 50mm



10: Qtr Panel nsr
Rusted
Over 5mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Tailgate
Dented
With Paint Damage



14: Wheel osr
Scratched
Up To 50mm



15: Qtr Panel osr
Scratched
Rusted



16: Door osr
Chipped
Edge Chip



17: Door osf
Scratched
Over 25mm Thru Paint



18: Door osf
Dented
Between 10mm + 30mm



19: Sill os
Rusted
Over 5mm



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
Chipped
1 To 5



22: Screen Front
Chipped
UpTo 10mm



23: Switches And Controls
Broken
Replace



24: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK