



# VEHICLE INSPECTION REPORT

**GK16DXO**

## Volkswagen Passat 2.0 TDI S 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	21/03/2016	Body Style	Estate	Last service miles	141,933
Year	2016	Keys	2	MOT Due	19/12/2026
Mileage	144,399 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	9		
VIN	WVVZZZ3CZGE163759	Last service date	13/04/2026		

£90 ADDITIONAL FEE  
 LAST SERVICE 13/04/2026 @ 141,933 MILES (9 SERVICES)

### Tyres

NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	6.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

### Features


- Bluetooth connection
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wing nsf  
Poor Previous Repair  
Poor Paint



4: Door nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Dented  
Over 30mm



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Qtr Panel nsr  
Dented  
With Paint Damage



8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



9: Tailgate  
Dented  
Over 30mm



10: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



11: Qtr Panel osr  
Dented  
Between 10mm + 30mm



12: Door osr  
Chipped  
1 To 5



13: Door osf  
Dented  
With Paint Damage



14: Wing osf  
Chipped  
1 To 5



15: Bonnet  
Dented  
Between 10mm + 30mm

### Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK