



# VEHICLE INSPECTION REPORT

**WM14VTO**

## Fiat 500 1.2 S 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE 5

### Details

Reg. date	30/06/2014	Body Style	Hatchback	Last service miles	76,493
Year	2014	Keys	2	MOT Due	14/01/2027
Mileage	86,619 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	5	Doors	3
VIN	ZFA3120000J217534	Last service date	14/08/2025		

£90 ADDITIONAL FEE

LAST SERVICE 14/08/2025 @ 76,493 MILES (5 SERVICES, 2 MAIN DEALER)

Fuel cut off unavailable message displayed

Airbag light is on

Rattle from exhaust/ heat shield

### Tyres

NSF	NEXEN	5.0mm
NSR	AUTOGRIP	5.0mm
OSF	NEXEN	5.0mm
OSR	AUTOGRIP	5.0mm


Spare

## Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
With Paint Damage



2: Bumper Front  
Cracked  
Over 25mm



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



5: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



6: A Post ns  
Chipped  
1 To 5



7: Door nsf  
Dented  
Over 30mm



8: Door nsf  
Chipped  
Edge Chip



9: Wheel nsr  
Scratched  
Over 50mm



10: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



11: Bumper Rear  
Scratched  
Over 100mm Thru Paint




12: Tailgate  
Dented  
With Paint Damage



13: Qtr Panel osr  
Dented  
With Paint Damage



14: Wheel osr  
Scratched  
Over 50mm




15: Door osf  
Dented  
Over 30mm



16: Wing osf  
Dented  
With Paint Damage



17: Roof  
Dented  
Over 30mm



18: Bumper Front Moulding  
Broken  
Replace



19: Seat Base Cover osf  
Scuffed  
Over 25mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK