



VEHICLE INSPECTION REPORT

LW19ACV

Nissan X-Trail 1.3 DiG-T N-Connecta 5dr DCT

nama
GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	21/05/2019	Body Style	Estate	Last service miles	55,592
Year	2019	Keys	2	MOT Due	17/05/2027
Mileage	68,331 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	7
Colour	GREY	Number of stamps	5		
VIN	JN1TGAT32U0000610	Last service date	04/04/2025		

Last Service - 04.04.2025 at 55592 miles (5 main dealer services) EML on, system voltage low

Tyres


NSF	BUDGET	6.0mm
NSR	PIRELLI	5.0mm
OSF	BUDGET	6.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Front TowEye Cvr
Missing
Replace



4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Screen Front
Cracked
Replace



7: Door nsf
Scratched
UpTo 25mm Thru Paint



8: Door nsf
Dented
Between 10mm + 30mm



9: Door nsr
Chipped
1 To 5



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Tailgate
Scratched
Over 25mm Thru Paint



13: Screen Rear
Scratched
UpTo 30mm



14: Bumper Rear
Cracked
Over 25mm



15: Bumper Rear Moulding
Broken
Replace



16: Qtr Panel osr
Dented
With Paint Damage



17: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



18: Wheel osr
Scratched
Over 50mm



19: Door osr
Scratched
Over 25mm Thru Paint



20: Door osf
Dented
Over 30mm



21: Door osf
Chipped
1 To 5



22: Wing osf
Dented
With Paint Damage



23: Wheel osf
Scratched
Up To 50mm



24: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



25: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		