



VEHICLE INSPECTION REPORT

GL11MXV

Skoda Yeti 1.2 TSI SE Plus 5dr

nama
 GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	30/06/2011	Body Style	Hatchback	Last service miles	85,637
Year	2011	Keys	2	MOT Due	Expired
Mileage	92,843 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	8	Doors	5
VIN	TMBKF75L8B6053533	Last service date	19/06/2024		

£90 ADDITIONAL FEE

Last service 19/06/2024 at 85,637 miles- 8 services (5 main dealer)
 Mileage of MOT in 2022 recorded incorrectly on MOT history
 MOT EXPIRED

Tyres

NSF	APLUS	4.0mm
NSR	RAPID	6.0mm
OSF	AUTOGRIP	3.0mm
OSR	AUTOGREEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Headrest Assy Rear Seat os
Missing
Replace



2: Headrest Assy Rear Seat Centr
Missing
Replace



3: Other
N/A
N/A



4: Bonnet
Scratched
Over 25mm Thru Paint



5: Bumper Front
Dented
With Paint Damage



6: Wing nsf
Dented
With Paint Damage



7: Wheel nsf
Scratched
Over 50mm



8: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



9: Door nsf
Dented
With Paint Damage



10: Door nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Scratched
Rusted



13: Tailgate
Scratched
Up To 25mm Thru Paint



14: Qtr Panel osr
Chipped
1 To 5



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Rusted
Over 5mm



17: Door osf
Rusted
Over 5mm



18: Wing osf
Dented
With Paint Damage



19: Roof
Rusted
Over 5mm



20: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



21: Bumper Reflector nsr
Broken
Replace



22: Switches And Controls
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK