



VEHICLE INSPECTION REPORT

GV14LYO

Kia Rio 1.25 VR7 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/06/2014	Body Style	Hatchback	Last service miles	110,465
Year	2014	Keys	2	MOT Due	30/06/2027
Mileage	112,301 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	WHITE	Number of stamps	1	Doors	5
VIN	KNADN511LE6963850	Last service date	18/03/2026		

£100 ADDITIONAL FEE

LAST SERVICE 18/03/2026 @ 110,465 MILES (1 SERVICE) Exhaust blowing

Tyres

NSF	BUDGET	5.0mm
NSR	SUNNY	5.0mm
OSF	BUDGET	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Dented
With Paint Damage



3: Bumper Front
Insecure
Action Required



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



13: Wheel osr
Corroded
Light



14: Door Pad nsf
Scuffed
Over 25mm



15: Door Pad osf
Scuffed
Over 25mm



16: Door nsr
Dented
Between 10mm + 30mm



17: Door osf
Dented
Over 30mm



18: Door osr
Chipped
Edge Chip



19: Door osf
Chipped
Edge Chip



20: Door osf
Dented
Between 10mm + 30mm



21: A Post osf
Chipped
1 To 5



22: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



23: Wheel osf
Scratched
Over 50mm



24: Wing osf
Chipped
Multiple Chips



25: Roof
Rusted
Over 5mm



26: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



27: Bumper Front Grill
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK