



# VEHICLE INSPECTION REPORT

GL17TWV

## Citroen C4 Picasso 1.2 PureTech Feel 5dr

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
3

### Details

Reg. date 30/06/2017

Year 2017

Mileage 102,516 Miles  
Warranted

Fuel Type Petrol

Colour BLUE

VIN VF73DHNMGJ771346

Body Style MPV

Keys 2

Service history Yes

Service documents Printout

Number of stamps 6

Last service date 05/02/2025

Last service miles 98,975

MOT Due 29/06/2025

CAP Clean £3,550.00

CAP Average £2,950.00

CAP Below £2,400.00

Gearbox MANUAL

Gears 6

£65 ADDITIONAL FEE AUX BELT REPLACED 10/02/2020 @ 38764 MILES Last service 05/02/2025 @ 98975 miles (6 MAIN DEALER SERVICES)

### Tyres

NSF MAXXIS 4.0mm

NSR MAXXIS 5.0mm

OSF MAXXIS 4.0mm

OSR MAXXIS 5.0mm

Spare

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Cruise control
- PAS
- Telephone
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Front parking sensor
- Rear parking sensor
- Trip computer
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Navigation system
- Rear wiper
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5

No Image

6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint




7: Door nsf  
Chipped  
1 To 5

No Image

8: Door nsf  
Scratched  
Over 25mm Not Thru Paint



9: Door nsr  
Chipped  
1 To 5



10: Door nsr  
Scratched  
Over 25mm Not Thru Paint



11: Wheel nsr  
Scratched  
Over 50mm



12: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



13: Bumper Rear  
Scratched  
Over 100mm Thru Paint



14: Boot Lid  
Scratched  
Over 25mm Thru Paint






15: Wheel osr  
Scratched  
Over 50mm




16: Qtr Panel osr  
Poor Previous Repair  
Paint Flake



17: Door osr  
Scratched  
Over 25mm Not Thru Paint



18: Door osf  
Chipped  
1 To 5



19: Door osf  
Scratched  
Over 25mm Not Thru Paint



20: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK