



VEHICLE INSPECTION REPORT

AU60XPX

Audi A4 1.8T FSI 160 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE 5

Details

Reg. date	30/09/2010	Body Style	Estate	Last service miles	54,117
Year	2010	Keys	2	MOT Due	31/10/2026
Mileage	161,296 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	12		
VIN	WAUZZZ8K8BA026105	Last service date	23/10/2025		

£90 ADDITIONAL FEE

LAST SERVICE 23/10/2025 @ 54,117 MILES (12 SERVICES, 3 MAIN DEALER) EML on, catalyst system efficiency below threshold, cylinder four misfire detected.

Drivers side window switch for window temperamental for putting the window up

Tyres

NSF	HANKOOK	4.0mm
NSR	HANKOOK	4.0mm
OSF	HANKOOK	4.0mm
OSR	HANKOOK	OK
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Trip computer
- Front fog lights
- Climate control
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Heated door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Alarm

Photos





Condition Check



Damage Photos



1: Wing of
Dented
Over 30mm



2: Wing of
Scratched
Over 25mm Thru Paint



3: Wheel osf
Scratched
Over 50mm



4: Bonnet
Dented
With Paint Damage



5: Bumper Front
Poor Previous Repair
Paint Flake



6: Bumper Front
Cracked
UpTo 25mm



7: Wheel nsf
Scratched
Over 50mm



8: Wing nsf
Dented
Over 30mm



9: Wing nsf
Scratched
Over 25mm Thru Paint



10: Door nsr
Rusted
Over 5mm



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



14: Bumper Rear
Scratched
Over 100mm Thru Paint



15: Qtr Panel osr
Dented
With Paint Damage




16: Wheel osr
Scratched
Over 50mm



17: Sill os
Dented
With Paint Damage



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osf
Dented
With Paint Damage



20: Door osf
Rusted
UpTo 5mm



21: Roof
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
 Average

Upholstery Condition
Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK