



VEHICLE INSPECTION REPORT

GX60CTK

Nissan Note 1.6 Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/10/2010	Body Style	MPV	Last service miles	63,512
Year	2010	Keys	2	MOT Due	12/10/2026
Mileage	65,907 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	13		
VIN	SJNFCAE11U2094412	Last service date	06/10/2025		

£90 ADDITIONAL FEE

Last Service - 06.10.2025 at 63512 miles (13 services)

Radio locked unable to check all features

Tyres


NSF	YOKOHAMA	2.0mm
NSR	NEXEN	5.0mm
OSF	YOKOHAMA	2.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear parking sensor
- Radio/CD
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Other
N/A
N/A



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsr
Dented
Over 30mm



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



12: Bumper Rear
Poor Previous Repair
Poor Paint



13: A Post ns
Dented
Between 10mm + 30mm




14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
Over 30mm



17: Roof
Scratched
Over 25mm Thru Paint



18: Door osf
Chipped
Edge Chip



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK