



VEHICLE INSPECTION REPORT

EF10BZC

Ford S-Max 2.0 TDCi 163 Titanium X Sport 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/05/2010	VIN	WF0SXXGBWSAJ06917	Last service miles	57,214
Year	2010	Body Style	MPV	MOT Due	01/10/2026
Mileage	140,715 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Number of stamps	5	Gears	6
Colour	GREY	Last service date	02/07/2015	Doors	5

Last Service - 02.07.2015 at 57214 miles (5 services) Mel light is on

Car been plugged in and detected:

Mass or volume air flow circuit A high input

Intake air temperature sensor 1 circuit high input

Cracked panoramic roof

Sat nav not working

Parking sensors faulty

Tyres

NSF	BUDGET	6.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Fascia Trim
Missing
Replace



3: Bonnet
Chipped
1 To 5



4: Bumper Front
Poor Previous Repair
Poor Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
UpTo 25mm Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsr
Dented
Between 10mm + 30mm



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Tailgate
Scratched
UpTo 25mm Thru Paint



15: Qtr Panel osr
Dented
With Paint Damage



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Chipped
Edge Chip



18: Door osf
Scratched
Over 25mm Thru Paint



19: Wing osf
Scratched
Up To 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm



22: Glass Roof
Cracked
Replace



23: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	Fault	Steering	OK