



VEHICLE INSPECTION REPORT

GV12FVF

Volvo V40 D2 SE Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	26/07/2012	Body Style	Hatchback	Last service miles	86,299
Year	2012	Keys	1	MOT Due	20/06/2027
Mileage	98,625 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	11	Doors	5
VIN	YV1MV8481D2001725	Last service date	30/01/2025		

Last service 30/01/2025 at 86,299 miles- 11 services (3 main dealer) Service overdue message displayed

Tyres

NSF	LAUFENN	5.0mm
NSR	KUMHO	5.0mm
OSF	LAUFENN	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
UpTo 25mm Thru Paint



7: Wheel nsr
Scratched
Up To 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear Moulding
Broken
Replace



10: Bumper Rear
Poor Previous Repair
Poor Paint



11: Tailgate
Scratched
Rusted




12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
 Scratched
 Over 25mm Thru Paint



16: Wheel osf
 Scratched
 Over 50mm



17: Wing osf
 Dented
 Between 10mm + 30mm



18: Door Mirror Assy osf
 Scratched (Painted)
 Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK