



VEHICLE INSPECTION REPORT

CF14BJX

Citroen C4 Picasso 1.6 e-HDi 115 Airdream Exclusive 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	11/08/2014	Body Style	MPV	Last service miles	78,444
Year	2014	Keys	2	MOT Due	Expired
Mileage	83,976 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	8	Doors	5
VIN	VF73D9HC8EJ707038	Last service date	28/06/2025		

£90 ADDITIONAL FEE

MOT EXPIRED

LAST SERVICE 28/06/2025 @ 78,444 MILES (8 SERVICES, 3 MAIN DEALER) Service spanner displayed

Rattle from exhaust or Heath shield

Tyres

NSF	NEXEN	5.0mm
NSR	RIKEN	5.0mm
OSF	NEXEN	5.0mm
OSR	RIKEN	5.0mm



Spare

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Park assist camera
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Other
N/A
N/A



12: Qtr Panel osr
Dented
Between 10mm + 30mm



13: Qtr Panel osr
Scratched
Up To 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Sill os
Dented
With Paint Damage



16: Door osr
Dented
Between 10mm + 30mm



17: Door osf
Chipped
Edge Chip



18: Door osf
Scratched
UpTo 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
		Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK