



# VEHICLE INSPECTION REPORT

**LR09RVE**

## Mercedes-Benz M-Class ML 280 CDI SPORT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	26/03/2009	Body Style	Estate	Last service miles	63,741
Year	2009	Keys	2	MOT Due	21/09/2026
Mileage	93,993 Miles Incorrect	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	7
Colour	SILVER	Number of stamps	8	Doors	5
VIN	WDC1641202A500926	Last service date	05/03/2019		

£90 ADDITIONAL FEE

last service 5/3/19 @ 63,741 miles ( 8 services 4 main dealer)

### Tyres

NSF	YOKOHAMA	5.0mm
NSR	BUDGET	4.0mm
OSF	YOKOHAMA	5.0mm
OSR	BUDGET	4.0mm

### Spare

## Features


- Cruise control
- Rear parking sensor
- Radio/CD
- Roof rails
- Electrically adjustable passenger seat
- Front head restraints
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Alarm
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Folding rear seats
- Height adjustable drivers seat
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front armrest
- Lumbar support
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- PAS
- Trip computer
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bumper Front  
Scratched  
Over 100mm Thru Paint



2: Bonnet  
Chipped  
Multiple Chips



3: Wheel osf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Screen Front  
Chipped  
UpTo 10mm



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Wheel nsr  
Scratched  
Up To 50mm



10: Bumper Rear  
Scratched  
Over 100mm Thru Paint



11: Tailgate  
Scratched  
Over 25mm Thru Paint



12: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



13: Door osf  
Scratched  
Up To 25mm Thru Paint



14: Seat Base Cover osf  
Torn  
Over 3mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK