



VEHICLE INSPECTION REPORT

KN15HTE

Vauxhall Mokka 1.6i Tech Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/04/2015	Body Style	Hatchback	Last service miles	39,195
Year	2015	Keys	2	MOT Due	08/10/2026
Mileage	64,430 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	5
Colour	WHITE	Number of stamps	1	Doors	5
VIN	W0LJC7EE3FB096162	Last service date	16/04/2021		

£90 ADDITIONAL FEE

LAST SERVICE 16/04/2021 @ 39,195 MILES (1 SERVICE, MAIN DEALER) Eml light is on
 Car been plugged in and detected:

Catalyst system efficiency below threshold
 (Bank 1)

Service due message displayed

Tyres


NSF	BUDGET	6.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Burn
Over 3mm



2: Other
N/A
N/A



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Dented
With Paint Damage



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Poor Previous Repair
Rippled Up To 30%



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



10: Tailgate
Chipped
1 To 5



11: Door osr
Chipped
Edge Chip



12: Wheel osr
Scratched
Over 50mm



13: Door osf
Chipped
Edge Chip



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Chipped
1 To 5



16: Wing nsf
Chipped
1 To 5



17: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK