



# VEHICLE INSPECTION REPORT

**GJ60FGO**

## Jaguar XF 3.0d V6 Luxury 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	01/09/2010	Body Style	Saloon	MOT Due	07/08/2026
Year	2010	Service history	Yes	Gearbox	AUTOMATIC
Mileage	68,186 Miles Warranted	Service documents	Service Book	Gears	6
Fuel Type	DIESEL	Number of stamps	10	Doors	4
Colour	GREY	Last service date	14/10/2024		
VIN	SAJAC0549BNR91505	Last service miles	59,152		

£90 ADDITIONAL FEE

LAST SERVICE 14/10/2024 @ 59,152 MILES (10 SERVICES, 5 MAIN DEALER)

### Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	4.0mm
Spare		

## Features


- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear armrest
- Metallic Paint
- Drivers airbag
- Alarm
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Trip computer
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- PAS
- Radio/CD
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



5: Door nsf  
Dented  
Between 10mm + 30mm



6: Door nsf  
Chipped  
1 To 5



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



10: Bumper Rear  
Scratched  
Up To 25mm Thru Paint




11: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



12: Wheel osr  
Scratched  
Up To 50mm



13: Door osr  
Scratched  
Over 25mm Thru Paint



14: Door osf  
Scratched  
UpTo 25mm Thru Paint



15: Door osf  
Dented  
Between 10mm + 30mm



16: Wing osf  
Scratched  
UpTo 25mm Thru Paint



17: Wheel osf  
Scratched  
Over 50mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK