



VEHICLE INSPECTION REPORT

RF16WLB

Ford Kuga 2.0 TDCi 180 Titanium 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/07/2016	Body Style	Hatchback	Last service miles	95,843
Year	2016	Keys	1	MOT Due	24/07/2026
Mileage	105,462 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	1	Doors	5
VIN	WF0AXXWPMFJ82104	Last service date	14/07/2025		

LAST SERVICE 14/07/2025 @ 95,843 MILES (1 SERVICE) Oil change required

Tyres

NSF	TRIANGLE	3.0mm
NSR	BUDGET	5.0mm
OSF	TRIANGLE	3.0mm
OSR	BUDGET	5.0mm

Spare

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage




2: Bumper Front
Poor Previous Repair
Paint Flake




3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Chipped
Edge Chip



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Chipped
Edge Chip



13: Door osr
Dented
Between 10mm + 30mm



14: Door osf
Dented
With Paint Damage



15: Wing osf
 Scratched
 Over 25mm Thru Paint



16: Wheel osf
 Scratched
 Over 50mm



17: A Post os
 Chipped
 1 To 5



18: Seat Back Cover osf
 Scuffed
 Over 25mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK