



VEHICLE INSPECTION REPORT

WF59KWG

Citroen C4 Picasso 1.6HDi 16V VTR Plus 5dr [5 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/09/2009	Keys	4	CAP Clean	£470.00
Year	2009	Service history	Yes	CAP Average	£200.00
Mileage	143,998 Miles Warranted	Service documents	Printout	CAP Below	£200.00
Fuel Type	Diesel	Number of stamps	4	Gearbox	MANUAL
Colour	BLUE	Last service date	22/07/2024	Gears	5
VIN	VF7UD9HZC9J158100	Last service miles	137,132		
Body Style	MPV	MOT Due	28/02/2026		

£50 ADDITIONAL FEE.

Last Service - 22.07.2024 at 137132 miles (4 services) Parking sensor fault

Tyres

NSF	NEXEN	4.0mm
NSR	HANKOOK	Worn
OSF	NEXEN	4.0mm
OSR	BUDGET	2.0mm
Spare		

Features


- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Dented
With Paint Damage



2: Boot Lid
Scratched
Over 25mm Not Thru Paint




3: Qtr Panel nsr
Dented
With Paint Damage



4: Wheel nsr
Scratched
Over 50mm




5: Door nsr
Chipped
1 To 5



6: Door nsr
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Chipped
1 To 5



8: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image



9: Wing nsf
Scratched
Over 25mm Not Thru Paint

10: Wheel nsf
Scratched
Over 50mm



11: Bonnet
Chipped
1 To 5



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: A Post ns
Poor Previous Repair
Paint Flake



14: A Post os
Rusted
Over 5mm

No Image



16: Wheel osf
Scratched
Over 50mm

No Image



18: Door osr
Dented
With Paint Damage

15: Wing osf
Scratched
Over 25mm Not Thru Paint



19: Qtr Panel osr
Dented
With Paint Damage



20: Wheel osr
Scratched
Over 50mm

No Image

No Image

21: Tyre nsr
Worn
Replace

22: Tyre nsr
Worn
Replace

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK