



# VEHICLE INSPECTION REPORT

**HY62SWV**

## Skoda Octavia 2.0T FSI vRS 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	03/09/2012	Body Style	Estate	Last service miles	117,193
Year	2012	Keys	1	MOT Due	02/09/2026
Mileage	136,811 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	6	Doors	5
VIN	TMBUF21ZXC2075239	Last service date	23/05/2024		

### £90 ADDITIONAL FEE

Last service 23/05/2024 at 117,193 miles- 6 services (3 main dealer) Eml light is on  
 Car been plugged in and detected  
 Intake manifold runner control circuit/ open  
 Passenger side front window faulty

### Tyres

NSF	BUDGET	3.0mm
NSR	ROADSTONE	2.0mm
OSF	CONTINENTAL	1.6mm
OSR	TRIANGLE	4.0mm

Spare

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Wheel of  
Scratched  
Over 50mm



2: Wing of  
Chipped  
1 To 5



3: Door Moulding osf  
Scratched (Painted)  
UpTo 25mm Thru Paint



4: Door osr  
Chipped  
1 To 5



5: Door osr  
Dented  
2 Or Less UpTo 10mm



6: Wheel osr  
Scratched  
Over 50mm



7: Bumper Rear  
Scratched  
Over 100mm Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Qtr Panel nsr  
Dented  
2 Or Less UpTo 10mm



10: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



11: Door nsf  
Dented  
2 Or Less UpTo 10mm



12: Wing nsf  
Dented  
With Paint Damage



13: Bumper Front  
Poor Previous Repair  
Poor Paint



14: Bonnet  
Chipped  
1 To 5



15: Door Pad osf  
Torn  
Over 10mm



16: Carpets Front  
Torn  
Over 10mm

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK