



VEHICLE INSPECTION REPORT

RJ61YOG

Hyundai I30 1.6 CRDi Premium 5dr



| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |

Details

| | | | | | |
|-----------|----------------------------|-----------------|-------------------|---------|--------|
| Reg. date | 29/12/2011 | VIN | TMADC81SLCJ088103 | Gearbox | MANUAL |
| Year | 2011 | Body Style | Estate | Gears | 6 |
| Mileage | 40,627 Miles Not Warranted | Keys | 2 | Doors | 5 |
| Fuel Type | DIESEL | Service history | None | | |
| Colour | WHITE | MOT Due | 08/01/2027 | | |

No service history
 Mileage not warranted- Inconsistencies in MOT mileages on MOT history

Tyres

| | | |
|-------|---------|-------|
| NSF | BUDGET | 5.0mm |
| NSR | HANKOOK | 5.0mm |
| OSF | BUDGET | 5.0mm |
| OSR | MAXXIS | 4.0mm |
| Spare | | |

Features


- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage



4: Bumper Front
Insecure
Action Required



5: Wing nsf
Dented
With Paint Damage



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Dented
With Paint Damage



8: Other
N/A
N/A



9: Door nsr
Dented
Between 10mm + 30mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Handle Outer nsr
Scratched (Painted)
Over 25mm Thru Paint



13: Bumper Rear
Cracked
Over 25mm



14: Tailgate
Scratched
UpTo 25mm Thru Paint



15: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Scratched
UpTo 25mm Thru Paint



18: Door osr
Dented
Between 10mm + 30mm



19: Door osf
Dented
Over 30mm



20: Wing osf
Dented
With Paint Damage



21: Wheel osf
 Scratched
 Over 50mm



22: C Post os
 Dented
 Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Windows | OK | Radio | OK |
| | | Steering | OK |