



# VEHICLE INSPECTION REPORT

**RE15BLJ**

## Ford Focus 1.6 125 Zetec 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE 5

### Details

Reg. date	12/05/2015	Body Style	Hatchback	Last service miles	72,892
Year	2015	Keys	1	MOT Due	19/03/2027
Mileage	82,018 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	7	Doors	5
VIN	WF05XXGCC5ER08349	Last service date	28/02/2025		

£90 ADDITIONAL FEE

Last Service - 28.025.2025 at 72892 miles (7 services) Gearbox clicks while driving

### Tyres

NSF	FARROAD	5.0mm
NSR	FARROAD	5.0mm
OSF	FARROAD	5.0mm
OSR	HABILEAD	5.0mm

Spare

### Features


- Bluetooth connection
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Radio/CD
- Space saver spare wheel
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Insecure  
Action Required



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint




4: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



5: Wheel nsf  
Scratched  
Over 50mm



6: Wing nsf  
Dented  
Between 10mm + 30mm



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Door nsr  
Poor Previous Repair  
Rippled Up To 30%



9: C Post ns  
Dented  
Between 10mm + 30mm



10: Wheel nsr  
Scratched  
Over 50mm



11: Qtr Panel nsr  
Dented  
Over 30mm



12: Bumper Rear  
Poor Previous Repair  
Poor Paint



13: B Post os  
Dented  
Over 30mm



14: Bumper Rear  
Cracked  
Over 25mm



15: Qtr Panel osr  
Poor Previous Repair  
Poor Paint



16: Wheel osr  
Scratched  
Over 50mm



17: Door osr  
Chipped  
1 To 5



18: Door osr  
Dented  
Between 10mm + 30mm



19: Door osf  
Dented  
Between 10mm + 30mm



20: Wing osf  
Chipped  
1 To 5



21: Wheel of  
Scratched  
Over 50mm



22: Screen Front  
Cracked  
Replace

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK