



VEHICLE INSPECTION REPORT

F1FSA

Land Rover Range Rover 5.0 V8 Supercharged Autobiography LWB 4dr Auto SS

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

nama
GRADE
2

Details

Reg. date	07/10/2014	Body Style	Estate	MOT Due	Expired
Year	2014	Keys	1	Gearbox	AUTOMATIC
Mileage	9,829 Miles Warranted	Service history	Yes	Gears	8
Fuel Type	Petrol	Number of stamps	5	Doors	5
Colour	BLACK	Last service date	25/01/2022		
VIN	SALGA3EE6EA187997	Last service miles	8,708		

Being sold on behalf of the High Court . Fitted with Chauffer pack and believed to have bullet proof glass. Copy of old V5 document .Registration number to be advised.

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Remote central locking
- Front parking sensor
- PAS
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Chipped
1 To 5

No Image

7: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Up To 50mm

No Image

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Chipped
Multiple Chips

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image


13: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image

14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Door osf
Dented
Over 2 UpTo 10mm



16: Wing osf
Scratched
Over 25mm Not Thru Paint



17: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		