



# VEHICLE INSPECTION REPORT

**SE14DUA**

## Nissan Qashqai 1.2 DiG-T Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply



### Details

Reg. date	17/07/2014	Body Style	Hatchback	Last service miles	23,384
Year	2014	Keys	2	MOT Due	28/06/2027
Mileage	73,701 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	2	Doors	5
VIN	SJNFEAJ11U1151089	Last service date	24/11/2017		

Last service 24/11/2017 at 23,384 miles- 2 main dealer services  
 NO V5 Engine overheating

### Tyres


NSF	BUDGET	Damaged
NSR	GT RADIAL	5.0mm
OSF	PIRELLI	Damaged
OSR	PIRELLI	5.0mm
Spare		

### Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

### Photos





## Condition Check



## Damage Photos



1: Roof Lining  
Scuffed  
Up To 25mm



2: Tyre osf  
Damaged  
Replace



3: Tyre nsf  
Damaged  
Replace



4: Bonnet  
Chipped  
Multiple Chips



5: Bumper Front  
Scratched  
25 to 100mm Thru Paint



6: Bumper Front  
Insecure  
Action Required



7: Wing nsf  
Dented  
With Paint Damage



8: Wing Front Arch Extension ns  
Missing  
Replace



9: Wheel nsf  
Scratched  
Over 50mm



10: Door Mirror Assy nsf  
Broken  
Replace



11: Door nsf  
Dented  
With Paint Damage



12: Door nsr  
Dented  
With Paint Damage



13: Wheel nsr  
Scratched  
Over 50mm



14: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



15: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



16: Bumper Rear  
Poor Previous Repair  
Paint Flake



17: Spoiler Rear  
Scratched (Painted)  
Over 25mm Thru Paint



18: Lamp osr  
Broken  
Replace



19: Qtr Panel osr  
Dented  
With Paint Damage



20: Wheel osr  
Scratched  
Over 50mm



21: Qtr Panel Arch Extension os  
Broken  
Replace



22: Door osr  
Dented  
With Paint Damage



23: Door osf  
Dented  
With Paint Damage




24: Wheel osf  
Scratched  
Over 50mm



25: Wing osf  
Scratched  
Over 25mm Thru Paint



26: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



27: Glass Roof  
Scratched  
Over 30mm

28: Switches And Controls  
Broken  
Replace

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                        Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK