



VEHICLE INSPECTION REPORT

GF72JYT

Vauxhall Grandland 1.6 Hybrid GS Line 5dr Auto

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/10/2022	Body Style	Hatchback	Last service miles	28,551
Year	2022	Keys	2	MOT Due	30/10/2026
Mileage	32,843 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Hybrid Electric	Service documents	Service Book	Gears	8
Colour	BLUE	Number of stamps	3	Doors	5
VIN	W0VZ4DGZXN6827280	Last service date	28/10/2025		

£90 ADDITIONAL FEE

Last service 28/10/2025 at 28,551 miles- 3 main dealer services

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	6.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	6.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Park assist camera
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



10: Tailgate
Scratched
Over 25mm Thru Paint



11: Qtr Panel Arch Extension os
Scratched (Painted)
UpTo 25mm Thru Paint




12: Door osr
Chipped
1 To 5



13: Door osf
Chipped
1 To 5



14: Screen Front
Chipped
UpTo 10mm



15: Roof
Chipped
1 To 5



16: B Post os
Dented
Between 10mm + 30mm



17: B Post os
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK