



VEHICLE INSPECTION REPORT

AK71BVL

MG Mg Hs EXCLUSIVE

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	30/09/2021	VIN	LSJA24U93MN110210	Last service date	12/04/2024
Year	2021	Body Style	Estate	Last service miles	20,467
Mileage	41,555 Miles Warranted	Service history	Yes	MOT Due	29/09/2026
Fuel Type	Petrol	Service documents	Printout	Gearbox	MANUAL
Colour	BLACK	Number of stamps	2	Gears	6

£90 ADDITIONAL FEE

Last service 12/04/2024 at 20,467 miles- 2 main dealer services

Tyres

NSF	FALKEN	3.0mm
NSR	MAXXIS	5.0mm
OSF	MICHELIN	2.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Telephone
- Electric door mirrors
- Roof rails
- Electrically adjustable passenger seat
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear parking sensor
- Trip computer
- Electric sunroof
- Air conditioning
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Lane departure warning
- Alarm
- Navigation system
- Rear wiper
- Radio/CD
- Front fog lights
- Climate control
- Front armrest
- Rear armrest
- Steering wheel reach adjustment
- Blind spot information
- Passenger airbag
- Remote central locking
- Park assist camera
- Steering wheel mounted controls
- Body coloured bumpers
- Opening panoramic glass roof
- Electrically adjustable drivers seat
- Front electric windows
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Leather seat trim

Photos





Condition Check



Damage Photos




1: Door osf
Dented
With Paint Damage



2: Door osf
Chipped
Edge Chip



3: Wing osf
Scratched
Over 25mm Thru Paint



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Bonnet
Dented
With Paint Damage



6: Screen Front
Chipped
UpTo 10mm



7: Door nsf
Dented
With Paint Damage




8: Wing nsf
Scratched
Over 25mm Thru Paint



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Door nsr
Dented
With Paint Damage



11: Wing Front Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



12: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



13: Wheel nsr
Corroded
Light



14: Bumper Rear
Poor Previous Repair
Poor Paint



15: Qtr Panel osr
Dented
With Paint Damage



16: Door osr
Dented
With Paint Damage

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		