



VEHICLE INSPECTION REPORT

YD64AAE

Mitsubishi Outlander 2.0 PHEV GX4hs 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2014	Body Style	Estate	Last service miles	126,706
Year	2014	Keys	2	MOT Due	26/11/2026
Mileage	135,124 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	HYBRID ELECTRIC	Service documents	Service Book	Gears	1
Colour	WHITE	Number of stamps	9	Doors	5
VIN	JMAXDGG2WEZC00901	Last service date	01/12/2025		

£100 ADDITIONAL FEE

last service 1/12/25 @ 126,706 miles (9 main dealer) Exhaust blowing
3 pin charging cable in boot

Tyres

NSF	BUDGET	6.0mm
NSR	RAPID	5.0mm
OSF	RAPID	3.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Cracked
Over 25mm



4: Wing nsf
Dented
Between 10mm + 30mm



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: A Post ns
Chipped
1 To 5



8: Door nsf
Dented
Over 30mm



9: Sill Panel Trim ns
Scratched (Painted)
Over 25mm Thru Paint



10: Door nsr
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Tailgate
Scratched
Up To 25mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint




16: Door osr
Dented
Over 30mm



17: Door osf
Dented
Over 30mm



18: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint




19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Chipped
1 To 5



21: Roof
Chipped
Multiple Chips



22: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		