



VEHICLE INSPECTION REPORT

AK58LAO

Nissan Note 1.6 Tekna 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	08/09/2008	Body Style	MPV	Last service miles	44,205
Year	2008	Keys	2	MOT Due	17/09/2026
Mileage	76,007 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Service Book	Gears	4
Colour	BLUE	Number of stamps	13	Doors	5
VIN	SJNFCAE11U1299006	Last service date	18/10/2022		

£90 ADDITIONAL FEE

Last service 18/10/2022 at 18/10/2022 at 44,205 miles- 13 services (9 main dealer)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wing osf
Scratched
Over 25mm Thru Paint



4: Wheel osf
Scratched
Over 50mm



5: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Other
N/A
N/A



7: Door osf
Scratched
UpTo 25mm Thru Paint



8: Door osr
Scratched
Rusted



9: Qtr Panel osr
Dented
With Paint Damage



10: Wheel osr
Scratched
Over 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Wiper Rear
Broken
Replace



13: Qtr Panel nsr
Dented
With Paint Damage



14: Wheel nsr
Scratched
Over 50mm



15: Door nsr
Dented
Over 30% Of Panel



16: Door Moulding nsr
Broken
Replace



17: Door nsf
Dented
With Paint Damage



18: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



19: Wing nsf
Dented
With Paint Damage



20: Wheel osf
Scratched
Over 50mm



21: Sunvisor ns
Torn
Over 10mm



22: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK