



VEHICLE INSPECTION REPORT

LG700BJ

Ford Focus 1.5 EcoBlue 120 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	Present



Details

Reg. date	05/10/2020	Body Style	Estate	Last service miles	100,264
Year	2020	Keys	2	MOT Due	04/10/2026
Mileage	102,806 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	9	Doors	5
VIN	WF0PXXGCHPLK02826	Last service date	06/05/2026		

Last Service -6.05.2026 at 100264 miles (9 services) Eml light is on
Car been plugged in and detected
NOx trap efficiency below threshold (Bank 1)

Tyres

NSF	SAILUN	6.0mm
NSR	SAILUN	6.0mm
OSF	SAILUN	6.0mm
OSR	SAILUN	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Service indicator
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Wing nsf
Dented
2 Or Less UpTo 10mm




8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsf
Dented
Between 10mm + 30mm




10: Door nsr
Dented
Over 30mm



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Lamp nsr
Broken
Replace



13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Tailgate
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint




16: Door osr
Dented
With Paint Damage



17: Door osf
Scratched
UpTo 25mm Thru Paint



18: Wing osf
Chipped
1 To 5



19: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK