



VEHICLE INSPECTION REPORT

YX68HVL

Volvo XC40 2.0 D3 R DESIGN 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/10/2018	Keys	2	CAP Clean	£12,000.00
Year	2018	Service history	Yes	CAP Average	£10,750.00
Mileage	94,437 Miles Warranted	Service documents	Service Book	CAP Below	£9,525.00
Fuel Type	Diesel	Number of stamps	2	Gearbox	MANUAL
Colour	BLUE	Last service date	17/02/2023	Gears	6
VIN	YV1XZ72V1K2088611	Last service miles	67,335		
Body Style	Estate	MOT Due	07/09/2025		

£100 ADDITIONAL FEE. Last Service: 17/02/2023 at 67335 miles. (2 main dealer services). Book & print. Eml on

Tyres

NSF	TOYO	4.0mm
NSR	BUDGET	5.0mm
OSF	TOYO	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim

Photos





Condition Check



Damage Photos




1: Carpets Front
Torn
Over 10mm




2: Bonnet
Dented
Over 2 UpTo 10mm



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Chipped
1 To 5



8: Door nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm

No Image

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint




13: Lamp nsr
Broken
Replace

No Image

14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Chipped
1 To 5



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Poor
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		