

### 46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT



# Ford Kuga 1.5 EcoBlue ST-Line X Edition 5dr

				nama
No	VAT	Margin		GRADE
	V5	Present		
23/01/2021	Body Style	Hatchback	CAP Below	£13,000.00
2021	Keys	2	Gearbox	MANUAL
33,071 Miles Warranted	Service history	None	Gears	6
Diesel	MOT Due	22/01/2026	Doors	5
GREY	CAP Clean	£15,650.00		
WF0FXXWPMFLS13058	CAP Average	£14,350.00		
	23/01/2021 2021 33,071 Miles Warranted Diesel GREY	23/01/2021Body Style2021Keys33,071 Miles WarrantedService historyDieselMOT Due	V5Present23/01/2021Body StyleHatchback2021Keys233,071 Miles WarrantedService historyNoneDieselMOT Due22/01/2026GREYCAP Clean£15,650.00	V5Present23/01/2021Body StyleHatchbackCAP Below2021Keys2Gearbox33,071 Miles WarrantedService historyNoneGearsDieselMOT Due22/01/2026DoorsGREYCAP Clean£15,650.00CAP Clean

## £100 ADDITIONAL FEE EML LIGHT ON SPANNER LIGHT ON ENGINE HAS A SLIGHT TAPPING NOISE

Tyres			
NSF	CONTINENTAL	Illegal	
NSR	TRIANGLE	5.0mm	
OSF	CONTINENTAL	2.0mm	
OSR	CONTINENTAL	3.0mm	
Spare			

## **Features**

#### • **Bluetooth connection**

- Navigation system
- Telephone
- Electric sunroof
- Front armrest
- Metallic Paint
- Traction control
- · Cloth seat trim
- Cruise control Park assist camera
- Radio/CD
- Air conditioning •
- Front electric windows
- ABS
- Tyre pressure monitor
- Léather seat trim
- Front parking sensor
- Rear parking sensor Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

- Heated front seat
- Rear wiper
- Electric door mirrors •
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking

## **Photos**




















# **Condition Check**



# Damage Photos





1: Wheel osf Corroded Light

2: Door osf Chipped Edge Chip





3: Qtr Panel osr Chipped 1 To 5



5: Wheel nsr Scratched Up To 50mm

Interior

**Carpet Condition Seat Condition** 

Average Average **Upholstery Condition** Odour

Scratched

11111

Scratched

6: Wheel nsf

Up To 50mm

Average No

## **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors. Please note buyers rate increase from 01/01/2025

Engine Runs OK	Gearbox 1st and Reverse Test OK
Brakes OK	Clutch Slip Test from Static OK
Turbo Boosting OK	Gearbox Static Gear Selection (engine running) OK
Parking Brake OK	No Excessive Smoking OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		