



VEHICLE INSPECTION REPORT

LV18KGE

Ford KA+ 1.2 Zetec 5dr

Cat: S
Inspection

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/04/2018	VIN	MAJUXXMTKUJL36602	Gearbox	MANUAL
Year	2018	Body Style	Hatchback	Gears	5
Mileage	70,549 Miles Warranted	Keys	1	Doors	5
Fuel Type	PETROL	Service history	None		
Colour	GREY	MOT Due	08/07/2027		

£100 ADDITIONAL FEE

NO SERVICE HISTORY

Category S Insurance Loss. Vehicle Structurally Damaged But Repairable-Insurer Decided Not to Repair

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	5.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cruise control
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wing nsf
Dented
Between 10mm + 30mm



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
Over 30mm



8: Door nsr
Dented
Between 10mm + 30mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Dented
With Paint Damage



11: Qtr Panel osr
Dented
With Paint Damage



12: Door osr
Poor Previous Repair
Poor Paint



13: Door osf
Poor Previous Repair
Rippled UpTo 30%



14: Wing osf
Poor Previous Repair
Poor Paint



15: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK