



VEHICLE INSPECTION REPORT

VK65O EZ

Nissan X-Trail 1.6 DiG-T N-Tec 5dr [7 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/09/2015	Keys	1	CAP Average	£4,050.00
Year	2015	Service history	Yes	CAP Below	£3,400.00
Mileage	106,930 Miles Warranted	Service documents	Service Book	Gearbox	MANUAL
Fuel Type	PETROL	Number of stamps	3	Gears	6
Colour	SILVER	Last service date	30/05/2024	Doors	5
VIN	JN1JDAT32U0000714	MOT Due	24/11/2026		
Body Style	Estate	CAP Clean	£4,725.00		

Last Service - 30.05.2024 at UNKNOWN miles (3 services) Noisy engine when idle
Oil low message displayed
Not original key
Aftermarket radio fitted
Airbag light is on


Tyres		
NSF	UNIROYAL	1.0mm
NSR	BUDGET	5.0mm
OSF	UNIROYAL	2.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
 - PAS
 - Digital radio
 - Opening panoramic glass roof
 - Folding rear seats
 - Height adjustable drivers seat
 - Steering wheel reach adjustment
 - Drivers airbag
 - Central locking
- Cruise control
 - Rear parking sensor
 - Body coloured bumpers
 - Roof rails
 - Front armrest
 - Rear electric windows
 - Metallic Paint
 - Isofix child seat anchor points
 - Remote central locking
- Front parking sensor
 - Rear wiper
 - Electric door mirrors
 - Space saver spare wheel
 - Front electric windows
 - Rear headrests
 - 3x3 point rear seat belts
 - Passenger airbag
 - Cloth seat trim
- Park assist camera
 - Steering wheel mounted controls
 - Front fog lights
 - Air conditioning
 - Front head restraints
 - Steering wheel rake adjustment
 - ABS
 - Side airbags
 - Alloy wheels

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Poor Previous Repair
Poor Paint



3: Bumper Front
Chipped
Multiple Chips



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Poor Previous Repair
Poor Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Tailgate
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Poor Previous Repair
Rippled UpTo 30%



16: Door osf
Scratched
UpTo 25mm Thru Paint



17: Wing osf
Scratched
UpTo 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK