

VEHICLE INSPECTION REPORT

KR58AFO

Toyota Land Cruiser 3.0 D-4D Invincible 5dr Auto [173]

| Inspection | | Vehicle | |
|-----------------|----|---------|--------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | TBC |



Details

| | | | | | |
|-----------|----------------------------|------------|-------------------|-------------|-----------|
| Reg. date | 18/12/2008 | VIN | JTEBZ29J600151877 | CAP Average | £4,800.00 |
| Year | 2008 | Body Style | Estate | CAP Below | £4,100.00 |
| Mileage | 147,099 Miles Warranted | Keys | 1 | Gearbox | AUTOMATIC |
| Fuel Type | Diesel | MOT Due | 25/03/2026 | Gears | 5 |
| Colour | BLACK | CAP Clean | £5,500.00 | | |

Slight noise from engine

Tyres

| | | |
|-------|-------------|-------|
| NSF | BRIDGESTONE | 3.0mm |
| NSR | BRIDGESTONE | 3.0mm |
| OSF | BRIDGESTONE | 4.0mm |
| OSR | BRIDGESTONE | 4.0mm |
| Spare | | |

Features


- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front head restraints
- ABS
- Remote central locking
- Park assist camera
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- Drivers airbag
- Leather seat trim
- PAS
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- 3x3 point rear seat belts
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



8: Door nsf
Chipped
1 To 5

No Image

9: Door nsf
Scratched
Over 25mm Not Thru Paint



10: Door nsr
Chipped
1 To 5

No Image

11: Door nsf
Scratched
Over 25mm Not Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Qtr Panel nsr
Chipped
1 To 5

No Image


14: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



15: Bumper Rear
Scratched
Over 100mm Thru Paint



16: Boot Lid
Rusted
Over 5mm




17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osf
Chipped
1 To 5



20: Door osf
Scratched
Over 25mm Not Thru Paint

No Image



21: Wing osf
Scratched
Over 25mm Not Thru Paint

22: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|------------------------------------------------|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Roof / sunroof | OK | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |