



VEHICLE INSPECTION REPORT

HV11SOU

Vauxhall Meriva 1.4i 16V SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/04/2011	Body Style	MPV	Last service miles	38,864
Year	2011	Keys	1	MOT Due	27/10/2026
Mileage	74,374 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	5	Doors	5
VIN	W0LSH9EC2B4023296	Last service date	03/08/2018		

£90 ADDITIONAL FEE

Last service 03/08/2018 at 38,864 miles- 5 services (4 main dealer) Code 16 warning displays brake light failure
Gearbox stiff when changing gears

Tyres

NSF	FALKEN	6.0mm
NSR	MATADOR	Damaged
OSF	MATADOR	6.0mm
OSR	MATADOR	6.0mm
Spare		

Features


- Cruise control
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Burn
Over 3mm



2: Seat Base Cover osf
Burn
UpTo 3mm



3: Seat Base Cover nsf
Burn
Over 3mm



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Chipped
1 To 5



8: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



9: Door nsf
Dented
With Paint Damage



10: Door nsr
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Over 50mm



13: Other
N/A
N/A



14: Bumper Rear
Poor Previous Repair
Paint Flake



15: Tailgate
Dented
Between 10mm + 30mm



16: Tailgate
Scratched
Over 25mm Thru Paint



17: Qtr Panel osr
Dented
With Paint Damage



18: Wheel nsr
Scratched
Over 50mm



19: Door osr
Dented
With Paint Damage



20: Door osf
Dented
With Paint Damage



21: Wheel osf
Scratched
Over 50mm



22: Wing osf
Chipped
1 To 5



23: Screen Front
Chipped
Over 10mm



24: Fascia Trim
Damaged
Replace



25: Switches And Controls
Broken
Replace



26: Door osf
Scratched
Over 25mm Thru Paint



27: Tyre nsr
Damaged
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Poor	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK