



VEHICLE INSPECTION REPORT

BU63UFL

Volkswagen Golf 1.6 TDI 105 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/09/2013	Body Style	Hatchback	Last service miles	122,719
Year	2013	Keys	2	MOT Due	15/09/2026
Mileage	123,096 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	5
Colour	WHITE	Number of stamps	9	Doors	5
VIN	WVWZZZAUZEP031559	Last service date	17/06/2026		

£90 ADDITIONAL FEE

Last service 17/06/2026 at 122,719 miles- 9 services

Tyre monitor faulty

Abs light is on

Exhaust blowing

Tyres

NSF	CONTINENTAL	2.0mm
NSR	MICHELIN	5.0mm
OSF	CONTINENTAL	2.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Bumper Front
Insecure
Action Required



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Roof
Chipped
Over 5mm



7: Wing nsf
Chipped
1 To 5



8: Door nsf
Rusted
Over 5mm



9: Door nsr
Chipped
1 To 5



10: A Post ns
Poor Previous Repair
Poor Paint



11: Door nsf
Poor Previous Repair
Rippled UpTo 30%



12: Qtr Panel nsr
Dented
With Paint Damage



13: Wheel nsr
Scratched
Over 50mm



14: Bumper Rear
Dented
With Paint Damage



15: Qtr Panel osr
Dented
With Paint Damage



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
Between 10mm + 30mm



18: Door osr
Chipped
1 To 5



19: Door osf
Scratched
Rusted



20: Wing osf
Chipped
1 To 5



21: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK