



VEHICLE INSPECTION REPORT

LT59RZJ

Land Rover Discovery 3.0 TDV6 XS 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	11/09/2009	Body Style	Estate	Last service miles	123,418
Year	2009	Keys	2	MOT Due	11/07/2027
Mileage	126,845 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	12	Doors	5
VIN	SALLAAAG3AA515147	Last service date	04/07/2025		

£90 ADDITIONAL FEE

LAST SERVICE 04/07/2025 @ 123,418 MILES (12 SERVICES, 5 MAIN DEALER)

17/07/2023 MOT IS IN KM Steering heavy

Tailgate will not open

Vehicle smokes

Tyres


NSF	PIRELLI	6.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	7.0mm
OSR	PIRELLI	6.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Wheel osf
Scratched
Up To 50mm



3: Wing osf
Chipped
1 To 5



4: Door osf
Chipped
1 To 5



5: Door osf
Chipped
Edge Chip



6: Door osr
Dented
Over 30mm



7: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Boot Lid
Poor Previous Repair
Poor Paint



10: Tailgate
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Up To 50mm



12: Door nsr
Chipped
1 To 5



13: Door nsf
Chipped
1 To 5




14: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



15: Wheel nsf
Scratched
Up To 50mm



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bonnet
Chipped
1 To 5



18: Roof
Dented
Over 30mm



19: Lamp osr
Broken
Replace



20: Door Pad osf
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	Fault