



VEHICLE INSPECTION REPORT

YT11NXH

Lexus CT 200h 1.8 SE-L Premier 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	16/03/2011	Body Style	Hatchback	MOT Due	Expired
Year	2011	Service history	Yes	Gearbox	CVT
Mileage	54,252 Miles Warranted	Service documents	Service Book	Gears	1
Fuel Type	HYBRID ELECTRIC	Number of stamps	12	Doors	5
Colour	SILVER	Last service date	12/08/2025		
VIN	JTHKD5BH302005029	Last service miles	51,915		

£100 ADDITIONAL FEE

MOT EXPIRED

Last service 12/08/2025 at 51,915 miles- 12 services (6 main dealer)

Book and print

Tyres



NSF	YOKOHAMA	3.0mm
NSR	FALKEN	4.0mm
OSF	YOKOHAMA	2.0mm
OSR	FALKEN	4.0mm
Spare		

Features


- Cruise control
- PAS
- Body coloured bumpers
- Climate control
- Front electric windows
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Leather seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Rear airbags
- Alloy wheels
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Lumbar support
- Steering wheel reach adjustment
- Curtain airbags
- Alarm

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Bumper Front
Cracked
Over 25mm



4: Bonnet
Chipped
Multiple Chips



5: Wheel nsf
Scratched
Over 50mm



6: A Post ns
Scratched
UpTo 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Bumper Rear
Poor Previous Repair
Paint Flake



10: Other
N/A
N/A



11: Wheel osr
Scratched
Over 50mm



12: Door osf
Rusted
UpTo 5mm



13: Door osr
Chipped
1 To 5



14: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK