



VEHICLE INSPECTION REPORT

EO67PPK

Ford Kuga 2.0 TDCi 180 Titanium X 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/09/2017	Keys	1	CAP Clean	£10,150.00
Year	2017	Service history	Yes	CAP Average	£9,025.00
Mileage	58,952 Miles Warranted	Service documents	Service Book	CAP Below	£7,875.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	AUTOMATIC
Colour	WHITE	Last service date	07/08/2024	Gears	6
VIN	WF0AXXWPMAC82947	Last service miles	58,952	Doors	5
Body Style	Hatchback	MOT Due	08/08/2025		

Last Service - 07.08.2024 at 53648 miles (7 services 1 main ealer services) sunroof not working , Exhaust Insecure

Tyres

NSF	BUDGET	4.0mm
NSR	CONTINENTAL	2.0mm
OSF	BUDGET	4.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Telephone
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Trip computer
- Electric door mirrors
- Climate control
- Front head restraints
- Rear headrests
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



2: Wheel nsr
Scratched
Up To 50mm

No Image

No Image

3: Door nsr
Scratched
Over 25mm Not Thru Paint

4: Door nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsr
Scratched
Up To 50mm

6: Bonnet
Chipped
Multiple Chips




7: Bumper Front
Poor Previous Repair
Poor Colour




8: Wheel osf
Scratched
Up To 50mm




9: Roof
Chipped
1 To 5



10: Door osf
Scratched
Over 25mm Not Thru Paint



11: Door osr
Scratched
Over 25mm Not Thru Paint



12: Boot Lid
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		