



VEHICLE INSPECTION REPORT

MM18JWD

Vauxhall Insignia 1.5T SRi Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	24/07/2018	Body Style	Hatchback	Last service miles	87,932
Year	2018	Keys	2	MOT Due	07/03/2027
Mileage	91,073 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	4	Doors	5
VIN	W0VZS6EB8J1177931	Last service date	05/03/2026		

£100 ADDITIONAL FEE

Last service 05/03/2026 at 87,932 miles- 4 services

Tyres		
NSF	BUDGET	5.0mm
NSR	WESTLAKE	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Fog Lamp Surrounds
Missing
Replace



3: Fogdriving Lamp osf
Broken
Replace



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Poor Previous Repair
Rippled UpTo 30%



8: Door nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Cracked
Replace



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Qtr Panel osr
Dented
Between 10mm + 30mm



13: Wheel osr
Scratched
Over 50mm



14: Door nsr
Dented
With Paint Damage



15: Door osf
Scratched
Over 25mm Thru Paint



16: Screen Front
Chipped
UpTo 10mm



17: Wing osf
Scratched
UpTo 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm



19: Bonnet
Chipped
1 To 5



20: Wing osf
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK