



VEHICLE INSPECTION REPORT

LR14JVJ

Toyota Prius+ 1.8 VVTi T4 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/03/2014	Keys	2	CAP Clean	£8,625.00
Year	2014	Service history	Yes	CAP Average	£7,625.00
Mileage	116,614 Miles Warranted	Service documents	Printout	CAP Below	£6,625.00
Fuel Type	Hybrid Electric	Number of stamps	4	Gearbox	CVT
Colour	GREY	Last service date	19/01/2023	Gears	1
VIN	JTDZS3EU903053177	Last service miles	89,991		
Body Style	MPV	MOT Due	21/09/2025		

£100 ADDITIONAL FEE

Last Service 19.01.2023 at 89991 miles (4 main dealer services) Suspension Knocking

Tyres

NSF	ZEETEX	4.0mm
NSR	ZEETEX	5.0mm
OSF	BUDGET	5.0mm
OSR	ZEETEX	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Steel wheels
- Cruise control
- Trip computer
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Chipped
1 To 5



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Sill ns
Dented
With Paint Damage



9: Bumper Rear
Dented
With Paint Damage



10: Boot Lid
Dented
Between 10mm + 30mm



11: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




13: Door osr
Dented
With Paint Damage




14: Door osf
Chipped
1 To 5



15: Wing osf
Chipped
1 To 5



16: Wing osf
Scratched
Over 25mm Not Thru Paint



17: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		