

# VEHICLE INSPECTION REPORT

**VA11OAD**

## Nissan Micra 1.2 DiG-S Tekna 5dr CVT

### Inspection

Serious Damage? No

### Vehicle

VAT Margin  
V5 Present

nama  
GRADE  
3

### Details

Reg. date	28/07/2011	Keys	2	CAP Clean	£4,200.00
Year	2011	Service history	Yes	CAP Average	£3,575.00
Mileage	33,626 Miles Warranted	Service documents	Printout	CAP Below	£2,975.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	CVT
Colour	WHITE	Last service date	26/04/2022	Gears	1
VIN	MDHFEUK13U0000875	Last service miles	28,128	Doors	5
Body Style	Hatchback	MOT Due	30/11/2025		

Last Service - 26.04.2022 at 28128 miles (1 services)

### Tyres


NSF	INFINITY	3.0mm
NSR	BRIDGESTONE	3.0mm
OSF	INFINITY	3.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Metallic Paint
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- ABS
- Remote central locking
- Front parking sensor
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Navigation system
- Radio/CD
- Air conditioning
- Rear headrests
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wheel osr  
Scratched  
Up To 50mm

No Image

3: Wheel nsr  
Scratched  
Up To 50mm

No Image


4: Wheel nsf  
Scratched  
Over 50mm

No Image

5: Door osf  
Chipped  
1 To 5



7: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



8: Bumper Rear  
Scratched  
Over 100mm Thru Paint






9: Qtr Panel nsr  
Chipped  
1 To 5




10: Door nsr  
Chipped  
Edge Chip



11: Door nsr  
Chipped  
1 To 5



12: Door nsf  
Chipped  
1 To 5



13: Wing nsf  
Dented  
2 Or Less UpTo 10mm



14: Bumper Front  
Scratched  
25 to 100mm Thru Paint




15: Bumper Front  
Scratched  
25 to 100mm Thru Paint



16: Bumper Front  
Scratched  
25 to 100mm Thru Paint



17: Bumper Front  
Scratched  
25 to 100mm Thru Paint



18: Bonnet  
Chipped  
1 To 5



19: Roof  
Poor Previous Repair  
Paint Flake



20: Door osr  
Dented  
Over 2 UpTo 10mm



21: Wing osf  
Dented  
Over 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
 Additional fees may apply to some vendors.  
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		