



VEHICLE INSPECTION REPORT

HV11ZYY

Hyundai I10 1.2 Classic 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/04/2011	Body Style	Hatchback	Last service miles	42,197
Year	2011	Keys	1	MOT Due	05/06/2027
Mileage	51,884 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	3	Doors	5
VIN	MALAN51CLBM835915	Last service date	04/06/2024		

£100 ADDITIONAL FEE

last service 4/6/24 @ 42,197 miles (3 services 1 main dealer) book & print
Date not recorded for first service in book. Eml light is on
Car been plugged in and detected
Camshaft position timing- over advanced or system performance (Bank 1)
Boot will not stay open

Tyres		
NSF	WINDFORCE	5.0mm
NSR	BUDGET	5.0mm
OSF	WINDFORCE	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Radio/CD
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Steel wheels
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Number Plate Front
Broken
Replace



3: Bumper Front
Chipped
1 To 5



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Lamp nsr
Broken
Replace



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Tailgate
Chipped
1 To 5



11: Qtr Panel osr
Dented
Between 10mm + 30mm



12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



13: Door osr
Scratched
UpTo 25mm Thru Paint



14: Door osr
Dented
Between 10mm + 30mm



15: Door osf
Scratched
UpTo 25mm Thru Paint



16: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK