



VEHICLE INSPECTION REPORT

MV66NNR

BMW X3 xDrive20d SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2016	Body Style	Estate	Last service miles	64,414
Year	2016	Keys	2	MOT Due	14/04/2027
Mileage	66,427 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	10	Doors	5
VIN	WBAWZ520900T57877	Last service date	07/04/2026		

£90 ADDITIONAL FEE

last service 7/4/26 @ 64,414 miles (10 services 5 main dealer)

Date recorded correctly on SETYRES invoice for 2026 Eml light is on

Car been plugged in and detected

Exhaust pressure sensor A circuit range / performance - Mass volume air flow A circuit range / performance- air flow too low

EGR A flow insufficient detected

Tyres


NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear wiper
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Door nsf
Chipped
1 To 5



5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Qtr Panel nsr
Chipped
1 To 5



7: Door nsr
Dented
Between 10mm + 30mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Other
N/A
N/A



10: Qtr Panel osr
Chipped
1 To 5



11: Door osr
Dented
With Paint Damage



12: Door osf
Chipped
Edge Chip




13: Wheel osf
Scratched
Over 50mm



14: Wing osf
Chipped
1 To 5



15: Screen Front
Chipped
UpTo 10mm



16: Roof
Dented
Over 30mm



17: Seat Back Cover osf
Scuffed
Over 25mm



18: Door Pad osf
Scuffed
Over 25mm



19: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK