



VEHICLE INSPECTION REPORT

EA71UJO

Mercedes-Benz Vito 85kW 41kWh Pure Van Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present



Details

Reg. date	22/11/2021	Keys	2	CAP Clean	£6,875.00
Year	2021	Service history	Yes	CAP Average	£6,150.00
Mileage	14,897 Miles Warranted	Service documents	Printout	CAP Below	£5,050.00
Fuel Type	ELECTRICITY	Number of stamps	1	Gearbox	AUTOMATIC
Colour	WHITE	Last service date	16/02/2023	Gears	1
VIN	W1V44760523929884	Last service miles	3,846		
Body Style	Panel Van	MOT Due	19/04/2027		

Last service 16/02/2023 at 3846 miles- 1 main dealer service Radio faulty
Type 2 charging cable

Tyres

NSF	DUNLOP	5.0mm
NSR	DUNLOP	5.0mm
OSF	DUNLOP	5.0mm
OSR	DUNLOP	5.0mm
Spare		

Features


- Park assist camera
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Dented
2 Or Less UpTo 10mm



2: Door osf
Poor Previous Repair
Rippled UpTo 30%



3: Door osf
Chipped
Edge Chip



4: Tailgate
Chipped
1 To 5



5: Door nsr
Dented
2 Or Less UpTo 10mm



6: Door nsf
Chipped
Edge Chip



7: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK