



VEHICLE INSPECTION REPORT

LD19FKE

Ford Mondeo 2.0 TDCi EConetic Titanium Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	Present



Details

Reg. date	04/03/2019	Body Style	Hatchback	Last service miles	58,533
Year	2019	Keys	2	MOT Due	21/01/2027
Mileage	60,146 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	7	Doors	5
VIN	WF0EXXWPCEKC88164	Last service date	22/12/2025		

Last Service - 22.12.2025 at 58533 miles (7 services)

Tyres

NSF	NEXEN	4.0mm
NSR	GENERAL TIRE	4.0mm
OSF	TOYO	3.0mm
OSR	WESTLAKE	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Telephone
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
Over 30mm



7: Door nsr
Poor Previous Repair
Rippled UpTo 30%




8: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Boot Lid
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Dented
Between 10mm + 30mm



12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
UpTo 25mm Thru Paint



15: Door osf
Dented
Between 10mm + 30mm



16: Door osf
Scratched
Over 25mm Thru Paint



17: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Roof
Chipped
1 To 5



21: Bonnet
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK