



VEHICLE INSPECTION REPORT

RK56UHP

Honda Civic 1.8 i-VTEC ES 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date	05/09/2006	Body Style	Hatchback	Last service miles	121,965
Year	2006	Keys	2	MOT Due	05/09/2026
Mileage	135,045 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	10	Doors	5
VIN	SHHFK27606U032206	Last service date	01/09/2023		

last service 1/9/23 @ 121,965 miles (10 services 4 main dealer) Radio screen faulty
Noisy Heath shield

Tyres

NSF	SAILUN	5.0mm
NSR	TOYO	4.0mm
OSF	SAILUN	5.0mm
OSR	TOYO	4.0mm
Spare		

Features


- Cruise control
- Radio/CD
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Fogdriving Lamp osf
Broken
Replace



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Dented
With Paint Damage



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Door nsr
Dented
Between 10mm + 30mm



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Dented
With Paint Damage



12: Tailgate
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Dented
With Paint Damage



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Dented
Between 10mm + 30mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osf
Dented
With Paint Damage



18: Door Mirror Assy osf
Broken
Replace



19: Wing osf
Scratched
Over 25mm Thru Paint



20: A Post os
Scratched
Over 25mm Thru Paint



21: Wheel nsf
Scratched
Over 50mm



22: Carpets Front
Scuffed
Over 25mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK