



VEHICLE INSPECTION REPORT

SE14DUA

Nissan Qashqai 1.2 DiG-T Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/07/2014	Body Style	Hatchback	Last service miles	23,384
Year	2014	Keys	2	MOT Due	28/06/2027
Mileage	73,701 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	2	Doors	5
VIN	SJNFEAJ11U1151089	Last service date	24/11/2017		

Last service 24/11/2017 at 23,384 miles- 2 main dealer services
Engine overheating

Tyres




NSF	BUDGET	Damaged
NSR	GT RADIAL	5.0mm
OSF	PIRELLI	Damaged
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Roof Lining
Scuffed
UpTo 25mm



2: Tyre osf
Damaged
Replace



3: Tyre nsf
Damaged
Replace



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Bumper Front
Insecure
Action Required



7: Wing nsf
Dented
With Paint Damage



8: Wing Front Arch Extension ns
Missing
Replace



9: Wheel nsf
Scratched
Over 50mm



10: Door Mirror Assy nsf
Broken
Replace



11: Door nsf
Dented
With Paint Damage



12: Door nsr
Dented
With Paint Damage



13: Wheel nsr
Scratched
Over 50mm



14: Qtr Panel nsr
Dented
Between 10mm + 30mm



15: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



16: Bumper Rear
Poor Previous Repair
Paint Flake



17: Spoiler Rear
Scratched (Painted)
Over 25mm Thru Paint



18: Lamp osr
Broken
Replace



19: Qtr Panel osr
Dented
With Paint Damage



20: Wheel osr
Scratched
Over 50mm



21: Qtr Panel Arch Extension os
Broken
Replace



22: Door osr
Dented
With Paint Damage



23: Door osf
Dented
With Paint Damage



24: Wheel osf
Scratched
Over 50mm



25: Wing osf
Scratched
Over 25mm Thru Paint



26: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



27: Glass Roof
Scratched
Over 30mm

28: Switches And Controls
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK