



VEHICLE INSPECTION REPORT

KX20PUJ

Suzuki Vitara 1.4 Boosterjet SZ-T 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	02/03/2020	Body Style	Hatchback	Last service miles	97,518
Year	2020	Keys	2	MOT Due	12/06/2027
Mileage	99,739 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	2	Doors	5
VIN	TSMLYDA1S00775767	Last service date	21/05/2026		

LAST SERVICE 21/05/2026 @ 97,518 MILES (2 SERVICES, BOTH MAIN DEALER)

Tyres

NSF	RAPID	2.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	2.0mm
OSR	BUDGET	4.0mm
Spare		


Features

- Bluetooth connection
- PAS
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Alarm

Photos



Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Chipped
Over 5mm



5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wiper Rear
Broken
Replace



9: Wheel osr
Scratched
Over 50mm



10: Qtr Panel osr
Chipped
1 To 5



11: Door osr
Chipped
1 To 5



12: Door osf
Chipped
Edge Chip



13: Door osf
Chipped
1 To 5



14: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



15: Wing osf
Chipped
1 To 5



16: Wing osf
Dented
Between 10mm + 30mm



17: Wheel osf
Scratched
Over 50mm



18: Screen Front
Cracked
Replace



19: Aperture Seal nsf
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK