



VEHICLE INSPECTION REPORT

MV58UNG

Ford Focus 1.6 Zetec 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/09/2008	Body Style	Hatchback	Last service miles	73,684
Year	2008	Keys	3	MOT Due	Expired
Mileage	95,793 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Service Book	Gears	4
Colour	BLUE	Number of stamps	9	Doors	5
VIN	WF0PXXGCDP8C50796	Last service date	10/08/2023		

Last service 10/08/2023 at 73,684 miles- 9 services Exhaust blowing
Gears very stiff to select
Bonnet will not open

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Rear wiper
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- Blind spot information
- Side airbags
- Alloy wheels
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Wheel osr
Scratched
Up To 50mm



7: Qtr Panel osr
Chipped
1 To 5



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Tailgate
Scratched
UpTo 25mm Thru Paint



10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Door nsr
Dented
With Paint Damage



13: Door nsf
Dented
With Paint Damage



14: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



15: Wing nsf
Dented
Between 10mm + 30mm



16: Wheel nsf
Scratched
Over 50mm



17: Bumper Front
Chipped
Multiple Chips

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK