



VEHICLE INSPECTION REPORT

LK64XRE

Vauxhall Corsa 1.4T Black Edition 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2014	Body Style	Hatchback	Last service miles	60,105
Year	2014	Keys	1	MOT Due	29/09/2026
Mileage	92,670 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	6	Doors	3
VIN	W0L0SDL08E6103643	Last service date	06/04/2022		

£90 ADDITIONAL FEE

Last service 06/04/2022 at 60,105 miles- 6 services Eml light is on
Car been plugged in and detected
A/C turbo / super charger boost sensor A circuit range

Tyres

NSF	FIRESTONE	5.0mm
NSR	FIRESTONE	5.0mm
OSF	FIRESTONE	5.0mm
OSR	FIRESTONE	Damaged
Spare		

Features


- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Service indicator
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Tyre osr
Damaged
Replace



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Chipped
Multiple Chips



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Poor Previous Repair
Poor Paint



10: Tailgate
Scratched
Over 25mm Thru Paint



11: Qtr Panel osf
Scratched
Over 25mm Thru Paint



12: Wheel osf
Scratched
Over 50mm



13: Door osf
Dented
With Paint Damage



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Chipped
1 To 5



16: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



17: Screen Front
Chipped
UpTo 10mm



18: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK