



VEHICLE INSPECTION REPORT

GY10WDS

Nissan Qashqai 1.6 Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/05/2010	Body Style	Hatchback	Last service miles	124,974
Year	2010	Keys	2	MOT Due	23/12/2026
Mileage	129,046 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	12	Doors	5
VIN	SJNFAAJ10U2057471	Last service date	19/12/2024		

Last service 19/12/2024 at 124,974 miles- 12 services (10 main dealer)
Book and print Bonnet will not open
Reverse camera faulty

Tyres

NSF	WESTLAKE	6.0mm
NSR	RIKEN	5.0mm
OSF	WESTLAKE	6.0mm
OSR	RIKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



3: Wing osf
Chipped
1 To 5



4: Door osf
Poor Previous Repair
Paint Flake




5: Door osr
Scratched
Over 25mm Thru Paint



6: Wheel osr
Scratched
Over 50mm



7: Lamp osr
Broken
Replace



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Poor Previous Repair
Paint Flake



10: Tailgate
Dented
With Paint Damage




11: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Chipped
1 To 5



14: Door nsf
Scratched
Over 25mm Thru Paint



15: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



16: Wing nsf
Scratched
Over 25mm Thru Paint



17: Wheel nsf
Scratched
Over 50mm



18: Bumper Front
Poor Previous Repair
Paint Flake



19: Bonnet
Scratched
Over 25mm Thru Paint



20: Screen Front
Chipped
UpTo 10mm



21: Door nsr
Dented
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK